

Electrical Checklist Report

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate

Asset Report Summary

APPLIANCE TYPE	STATUS	QUOTE REQUIRED	URGENCY
Switchboard	Compliant	Yes	Low
Light Switches	Compliant	No	N/A
Light Fittings	Compliant	No	N/A
Power Points	Compliant	No	N/A
Oven	Compliant	No	N/A
Rangehood	Compliant	No	N/A
Air Conditioner	Compliant	No	N/A
Dishwasher	Compliant	No	N/A



PROPERTY ADDRESS:

DATE OF INSPECTION:

2023 CLIENT: Square Investments Real Estate

ASSET CHECKLIST

SWITCHBOARD	
CHECKLIST	
Are Safety Switches / Circuit Breakers Installed	PASS
Switchboard Condition	PASS
Earth System	PASS
Fire Caulking	PASS
Labels And Pole Fillers	PASS
Mechanical Protection On Cables	PASS
Incoming Mains / POA	PASS
Has All Information/Images Been Uploaded And Recorded	PASS

NOTES

Recommend upgrading unprotected sub-circuits to RCBO's. (Clause 2.6.3.2.2) $1x\ 20A$ (Oven circuit)

PHOTO/S









PROPERTY ADDRESS:

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate

LIGHT SWITCHES

CHECKLIST	
Switch Mechanism	PASS
Switch Functionality / Location	PASS
Wall Plate Condition	PASS
Dimmer	N/A

NOTES

PHOTO/S











PROPERTY ADDRESS:

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate

LIGHT FITTINGS

CHECKLIST	
Functionality	PASS
Exhaust Fan	PASS
Cover / Difuser	PASS
Fixings	

NOTES	

PHOTO/S











PROPERTY ADDRESS:

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate

POWERPOINTS

CHECKLIST	
Switch Mechanism	PASS
Wall Plate Condition	PASS
Functionality	PASS
Polairty/Earth	PASS
Location	PASS

NOTES

PHOTO/S











PROPERTY ADDRESS:

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate

OVEN

CHECKLIST	
On / Off Function	PASS
Location	PASS
Fixings	

NOTES

Recommend replacement of globe in the oven.

PHOTO/S







PROPERTY ADDRESS:

DATE OF INSPECTION:

2023 CLIENT: Square Investments Real Estate

RANGEHOOD

CHECKLIST	
On / Off Function	PASS
Location	PASS
Fixings	PASS

NOTES	

PHOTO/S







PROPERTY ADDRESS:

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate

AIR CONDITIONER

CHECKLIST	
On / Off Function	PASS
Location	PASS
Fixings	PASS

NOTES	

PHOTO/S







PROPERTY ADDRESS:

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate

DISHWASHER

CHECKLIST	
Condition	PASS
Functionality	PASS
Polairty/Earth	PASS
Location	PASS

NOTES

PHOTO/S



Further Comments



PROPERTY ADDRESS:

DATE OF INSPECTION: 2023

CLIENT: Square Investments Real Estate